

ASBESTOS ASSES SURVEY

H-K Building #: 21

Project Number: 0980193E
Project: G. HEILEMAN BREWERY "E"

Date Inspected: 03/21/89 Inspector: TIM SWARTZ Building Number: 21/22

Building Name: BREWHOUSE/STOCK CELLARS SEATTLE. WASHINGTON

Building Type: BREW/STOCK

Year Constructed: 1948

****	AREA NUMBER: 01	AREA DESC	RIPTION	: Ground Floor-Part #21-Spen	nt Grain R	oom	AREA AVERAG	X ASBE	stos:	22X		*****	***
LOCATION OF	THE MATERIAL	SAMPLE	ASB	MATERIAL DESCRIPTION	O&M CODE	QUANTITY	UNITS OF MEASURE	PIPE		PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS

LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	UNITS OF QUANTITY MEASURE	PIPE ID	EXP POT	PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
above caustic tank & along east wall	00-356573		pipe covering	OMA	50 ft. 4 in. O.D.		27	111	\$446	\$279	\$725
southeast area-by caustic tank	00-356577		pipe covering	OMA	30 ft. 8 in. O.D.						
above caustic tank & along south wall	00-356581		wrapped cardboard/paper pipe	OMA	42 ft. 8 in. O.D.			111	\$594		\$1,019
center E to W-along beam-at ceiling	00-356585		wrapped cardboard/paper pipe	OMA	25 ft. 6 in. O.D.			111	\$324		\$527
along east wall-near ceiling	00-356585		wrapped cardboard/paper pipe	OMA	70 ft. 4 in. 0.D.			111	\$624	\$391	\$1,015
near north entrance	00-356585		wrapped cardboard/paper pipe	AMO	26 ft. 8 in. O.D.			111	\$368	\$263	\$631
above caustic tank & along east wall	00-356585		wrapped cardboard/paper pipe	AMO	30 ft. 4 in. O.D.			111	\$268	\$167	\$435
center N to S-along beam-at ceiling	00-356585		wrapped cardboard/paper pipe	OMA	12 ft. 4 in. 0.D.			111	\$107	\$67	\$174
above caustic tank & along east wall	12-356574		mjp on pipe covering	OMA	20 4 in. O.D.	HPS/R	27		\$562	\$312	\$874
	12-356575	10%						111			
	12-356576	25%	1					111			
southeast area-by caustic tank	13-356578		mjp on pipe covering	OMA	3 8 in. O.D.	D₩		111	\$144	\$85	\$229
	13-356579	0%						111			
	13-356580	0%	in the second se					111			
above caustic tank & along south wall	14-356582		mjp on wrapped cardboard/paper	OMA	70 8 in. O.D.	DW		111	\$3,369	\$1,981	\$5,350
	14-356583	40%	i					111			
	14-356584	50%	i.					111			
near north entrance	15-356586		mjp on wrapped cardboard/paper	OMA	2 8 in. O.D.	DW		111	\$96	\$57	\$153
along east wall-near ceiling	15-356586	50%	mjp on wrapped cardboard/paper	OMA	10 4 in. O.D.	D₩		111	\$281	\$156	\$437
above caustic tank & along east wall	15-356586	50%	mjp on wrapped cardboard/paper	OMA	6 4 in. O.D.	DW	27		\$169	\$94	\$263
center E to W-along beam-at ceiling	15-356586		mjp on wrapped cardboard/paper	OMA	1 6 in. O.D.	DW		111	\$39	\$23	\$62
center N to S-along beam-at ceiling	15-356586		mjp on wrapped cardboard/paper	OMA	1 4 in. O.D.	DW		111]	\$28	\$16	\$44
	15-356587	60%					27				
	15-356588	60%					27	111			

AREA COMMENTS

AREA # 01 TOTAL \$7,419 \$4,519 \$11,938

The materials are in fair condition with minor localized contact and water damage. The materials are approximately 5' to 14' from the floor. At a minimum, it is recommended that the materials be properly repaired and monitored. If removal is planned, gross removal procedures are recommended. This appears to be a medium traffic area.

*******	AREA NUMBER: 02	AREA DESCRIPTION: Ground Floor	AREA AVERAGE % ASBESTOS: 27%	*******
			· · · · · · · · · · · · · · · · · · ·	

LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	0&M CODE	QUANTITY	UNITS O	F PIPE	EXP POT	- 1	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
part 21-brew kettle rm-under S kettle part 21-brew kettle rm-under S kettle	00-356573 00-356573		pipe covering pipe covering	OMA OMA			O.D. HPS/					\$1,160 \$106

HALL-KIMBRELL ENVIRONMENTAL INC.

Page 44



SURVEY ASBESTOS ASSE

H-K Building #: 21
Project Number: 0980193E
Project: G. HEILEMAN BREWERY "E"
Date Inspected: 03/21/89
Inspector: TIM SWARTZ

Building Number: 21/22
Building Name: BREWHOUSE/STOCK CELLARS
SEATTLE, WASHINGTON
Building Type: BREW/STOCK
Year Constructed: 1948

part 21-west wall	00-356573		pipe covering	OMA	20 ft. 6 in. O.D.		26 111	\$260	\$162	\$422
stairwell in part 21	00-356573	25%	pipe covering	OHA	5 ft. 4 in. O.D.		26 111	\$45	\$28	\$73
stairwell in part 21	00-356573	25%	pipe covering	OMA	3 ft. 6 in. O.D.			\$39	\$24	\$63
part 21-brew kettle rm-under N kettle	00-356573		pipe covering	OMA	45 ft. 4 in. O.D.			\$401	\$251	\$652
part 21-brew kettle rm-under N kettle	00-356573	25%	pipe covering	OMA	16 ft. 6 in. O.D.		26 111	\$208	\$130	\$338
part 21-against south wall-along ceiling	00-356573	25%	pipe covering	OHA	20 ft. 4 in. O.D.	HPS/R	26 111	\$178	\$112	\$290
part 21-brew kettle rm-along east wall	00-356573	25%	pipe covering	OMA	45 ft. 4 in. O.D.	HPS/R	26 111	\$401	\$251	\$652
part 22-cellar H stock-along east wall	00-356573	25%	pipe covering	OMA	180 ft. 4 in. O.D.	HPS/R	26 111	\$1,606	\$1,004	\$2,610
part 22-cellar H stock-along east wall	00-356573	25%	pipe covering	OMA	180 ft. 8 in. O.D.	HPS/R	26 111	\$2,547	\$1,820	\$4,367
part 21-west wall	00-356573	25%	pipe covering	OMA	40 ft. 8 in. O.D.	HPS/R	26 111	\$566	\$404	\$970
part 21-brew kettle room-catwalk	00-356573	25%	pipe covering	OMA	130 ft. 4 in. O.D.		26 111	\$1,160	\$725	\$1,885
part 21-brew kettle room-catwalk	00-356573	25%	pipe covering	OMA	88 ft. 6 in. O.D.	HPS/R	26 111	\$1,142	\$714	\$1,856
part 21-west wall	00-356573	25%	pipe covering	OMA	40 ft. 4 in. O.D.	HPS/R	26 111	\$357	\$223	\$580
stairwell in part 21	00-356573	25%	pipe covering	OMA	3 ft. 10 in. 0.D	HPS/R	26 111	\$57	\$42	\$99
pt 21-brew kettle rm-catwalk-ctr&E wall	00-356577	0%	pipe covering	OMA	35 ft. 4 in. O.D.	D₩	ļ			
pt 21-brew kettle rm-catwalk-ctr&E wall	00-356577	0%	pipe covering	OMA	10 ft. 6 in. O.D.	D₩	1			1
part 21-against south wall-along ceiling	00-356577	0%	pipe covering	OMA	25 ft. 8 in. O.D.	DW				ļ
part 21-brew kettle rm-northeast area	00-356589		pipe covering	OHA	25 ft. 6 in. O.D.		26 111	\$324	\$203	\$527
part 21-brew kettle rm-kettle at N end	01-356463	50%	boiler/tank insulation	OMB	830 sq.ft.		26 111	\$23,448	\$18,783	\$42,231
part 21-brew kettte im-kettte at k old	01-356464	35%	Sorter, tank moderation		555 54		26 111	,		
J	01-356465	35%	j				26 111			,
24 tany bassle amphassle as C and	02-356466	40%	boiler/tank insulation	OMB	830 sq.ft.		26 111	\$23,448	\$18,783	\$42,231
part 21-brew kettle rm-kettle at S end	02-356467	40%	Dorter, tank made at ton	G.10	050 54		26 111	0207110	0.07.00	,
}	02-356468	40%	}				26 111			j
part 21-brew kettle room-catwalk	12-356574	15%	mip on pipe covering	OMA	16 4 in. O.D.	HPS/R	26 111	\$449	\$250	\$699
part 22-cellar H stock-along east wall	12-356574	15%	mjp on pipe covering	OMA		HPS/R	26 111	\$193	\$113	\$306
	12-356574	15%	mjp on pipe covering	OHA		HPS/R	26 111	\$562	\$312	\$874
part 21-brew kettle rm-under S kettle	12-356574	15%	mjp on pipe covering	OMA		HPS/R	26 111	\$140	\$78	\$218
part 21-west wall	12-356574	15%	mip on pipe covering	OMA		HPS/R	26 111	\$63	\$39	\$102
stairwell in part 21 part 22-cellar H stock-along east wall	12-356574	15%	mjp on pipe covering	OMA		HPS/R	26 111	\$112	\$62	\$174
	12-356574	15%	mjp on pipe covering	OMA		HPS/R	26 111	\$112	\$62	\$174
part 21-against south wall-along ceiling	12-356574	15%	mip on pipe covering	OHA		HPS/R	26 111	\$421	\$234	\$655
part 21-brew kettle rm-under N kettle	12-356574	15%	mjp on pipe covering	OMA		HPS/R	26 111	\$193	\$113	\$306
part 21-west wall				OMA		HPS/R	26 111	\$774	\$454	\$1,228
part 21-brew kettle room-catwalk	12-356574	15%	mjp on pipe covering	OMA		HPS/R	26 111	\$39	\$23	\$62
stairwell in part 21	12-356574	15%	mjp on pipe covering				26 111	\$28	\$16	\$44
stairwell in part 21	12-356574	15%	mjp on pipe covering	OMA		HPS/R	26 111	\$281	\$156	\$437
part 21-brew kettle rm-along east wall	12-356574	15%	mip on pipe covering	OMA		HPS/R		\$309	\$182	\$491
part 21-west wall	12-356574	15%	mjp on pipe covering	OMA	8 6 in. O.D.	HP5/K	26 111	2303	₹102	7771
'	12-356575	10%	!				26 111			i
	12-356576	25%					26 111	****	*425	\$350
pt 21-brew kettle rm-catwalk-ctr&E wall	13-356578	0%	mip on pipe covering	OMA		DW	26 111	\$225	\$125	\$153
part 21-against south wall-along ceiling	13-356578	0%	mjp on pipe covering	OMA	2 8 in. 0.D.	DW	26 111	\$96	\$57	≯133
	13-356579	0%	1				26 111			1
	13-356580	0%					26 111			
part 21-brew kettle rm-northeast area	16-356590	40%	mjp on pipe covering	OMA	12 6 in. O.D.	PL	26 111	\$464	\$273	\$737
	16-356591	0%	{				26 111			ł
j	16-356592	40%					26 111			ļ
	17-356593		boiler/tank insulation	OMB	90 sq.ft.					

HALL-KIMBRELL ENVIRONMENTAL INC.

Page 45



T SURVEY ASBESTOS ASS

Project Number: 0980193E

Project: G. HEILEMAN BREWERY "E"

Date Inspected: 03/21/89 Inspector: TIM SWARTZ Building Number: 21/22

Building Name: BREWHOUSE/STOCK CELLARS

SEATTLE, WASHINGTON
Building Type: BREW/STOCK
Year Constructed: 1948

part 21-brew kettle rm-3M CIP tank-north	17-356594 17-356595 18-356596 18-356597 18-356598	0% 0% 40% 50% 40%	boiler/tank insulation	ОМВ	86 sq.ft.	26 111 26 111 26 111	\$2,430	\$1,946	\$4,376	
--	---	-------------------------------	------------------------	-----	-----------	----------------------------	---------	---------	---------	--

AREA COMMENTS

AREA # 02 TOTAL \$63,857 \$48,641 \$112,498

The materials are in fair to good condition with minor contact and water damage. The materials are approximately 1' to 10' from the floor. At a minimum, it is recommended that the materials be repaired and monitored. If removal is planned, extensive gross removal procedures are recommended. This appears to be a high traffic area.

******	AREA NUMBER: 03	AREA DESCRIPTION: 2nd Floor-Part #21	AREA AVERAGE % ASBESTOS: 35%	******

LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	QUANTITY	UNITS OF MEASURE	P I I			REMOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
stairwell between 1st & 2nd floors	00-356472	30%	pipe covering	OMA	20 f	t. 4 in. (O.D. HPS	/R 26	111	\$178	\$112	\$290
stairwell between 1st & 2nd floors	00-356472	30%	pipe covering	OMA	` 8 f	t. 10 in.	O.D HPS	/R 26	111	\$151	\$112	\$263
stairwell between 1st & 2nd floors	00-356472	30%	pipe covering	OMA	8 f	t. 12 in.	O.D HPS	/R 26	111	\$176		\$311
kettle room-north area	00-356472		pipe covering	OMA	140 f	t. 4 in. (O.D. HPS	/R 26	111	\$1,249		\$2,030
kettle room-north area	00-356472		pipe covering	OMA		t. 6 in. (111	\$208	\$130	\$338
kettle room-north area	00-356472		pipe covering	AMO		t. 8 in. (111	\$212	\$152	\$364
kettle room-mezzanine-along south wall	00-356472		pipe covering	OMA		t. 12 in.			111	\$220		\$389
kettle room-mezzanine-along north wall	00-356472		pipe covering	OMA		t. 6 in. (111	\$65	\$41	\$106
kettle room-hops storage	00-356472		pipe covering	OMA		t. 4 in. (111	\$357	\$223	\$580
kettle room-mezzanine-along south wall	00-356472		pipe covering	AMO		t. 10 in.			111	\$189		\$329
kettle room-mezzanine-along north wall	00-356472		pipe covering	OMA		t. 8 in. (111	\$424	\$303	\$727
kettle room-mezzanine-against east wall	00-356472		pipe covering	OMA		t. 8 in. (111	\$255		\$437
kettle room-mezzanine-against south wall	00-356476	40%	wrapped cardboard/paper pipe	OMA	10 f	t. 8 in. (D.D. DW	26	$-\Pi\Pi$	\$141	\$101	\$242
kettle room-break room	00-356476	40%	wrapped cardboard/paper pipe	OMA		t. 6 in. (26	111	\$13	\$8	\$21
kettle room-break room	00-356476	40%	wrapped cardboard/paper pipe	OMA	10 f	t. 8 in. (D.D. DW		Ш	\$141	\$101	\$242
kettle room-hops storage-northeast area	00-356476	40%	wrapped cardboard/paper pipe	AMO	10 f	t. 6 in. (Wd .d.c	26	111	\$130	\$81	\$211
stairwell between 1st & 2nd floors	04-356473		mjp on pipe covering	OMA	6 4	in. 0.D.	HPS	/R 26	111	\$169	\$94	\$263
kettle room-north area	04-356473	50%	mjp on pipe covering	AMO	4 6	in. 0.D.	HPS	/R 26	111	\$155	\$91	\$246
stairwell between 1st & 2nd floors	04-356473	50%	mjp on pipe covering	AMO	2 1	0 in. 0.D.	. HPS	/R 26	111	\$125	\$78	\$203
kettle room-mezzanine-along north wall	04-356473	50%	mjp on pipe covering	OMA	6 6	in. O.D.	HPS	/R 26	111	\$232	\$136	\$368
kettle room-mezzanine-along north wall	04-356473	50%	mjp on pipe covering	OMA	5 8	in. 0.D.	HPS	/R 26	111	\$241	\$141	\$382
stairwell between 1st & 2nd floors	04-356473	50%	mjp on pipe covering	OMA	2 1	2 in. 0.D.	. HPS	/R 26	111	\$152	\$95	\$247
kettle room-north area	04-356473		mip on pipe covering	OMA		in. O.D.	HPS		111	\$337	\$187	\$524
kettle room-hops storage-south area	04-356473		mjp on pipe covering	OHA		in. O.D.	HPS		111	\$337	\$187	\$524
kettle room-north area	04-356473		mip on pipe covering	OMA		in. 0.D.	HPS		iii	\$144	\$85	\$229
kettle room-mezzanine-against east wall	04-356473		mjp on pipe covering	OMA		in. 0.D.	HPS		111	\$193		\$306
notite toom men-entitle against east water	04-356474	50%	myp on pipe covering	ψ. IA	4 0		117 .		iii	1	V.1.5	4500
•	04-356475	60%							111			

HALL-KIMBRELL ENVIRONMENTAL INC.

Page 46

H-K Building #: 21

ASBESTOS ASSE

Building Number: 21/22

Building Name: BREWHOUSE/STOCK CELLARS

SEATTLE, WASHINGTON

Building Type: BREW/STOCK Year Constructed: 1948

26 111

Project: G. HEILEMAN BREWERY "E"
Date Inspected: 03/21/89
Inspector: TIM SWARTZ

Project Number: 0980193E

kettle room-break room 05-356477 60% mjp on wrapped cardboard/paper OMA 1 8 in. O.D. 26 111 \$28 \$76 kettle room-break room 05-356477 60% mjp on wrapped cardboard/paper OMA 2 6 in. O.D. DW 26 111 \$77 \$45 \$122 05-356478 50% 26 111 05-356479 50% 26 111 06-356480 50% boiler/tank insulation OMB 550 sq.ft. \$27,984 kettle room-break room-whirlpool 26 111 \$15,538 \$12,446 06-356481 10% 26 111

AREA COMMENTS

AREA # 03 TOTAL \$21,857 \$16,497 \$38,354

The materials are in good condition with minor contact and water damage. The materials are approximately 1' to 18' from the floor. At a minimum, it is recommended the materials be repaired and monitored. If removal is planned, gross removal procedures are recommended. This appears to be a high traffic area.

40%

06-356482

LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE			EXP POT	PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
below mash tub	00-356495		pipe covering	OHA	55 ft. 4 in. O.D. H		28	111	\$491	\$307	\$798
below mash tub	, 00-356495	30%	pipe covering	OMA	35 ft. 6 in. O.D. H		28		\$454	\$284	\$738
north of mash filter	00-356495	30%	pipe covering	OMA	6 ft. 4 in. O.D. H		28	1	\$54	\$33	\$87
south of mash filter	00-356495	30%	pipe covering	AMO	10 ft. 8 in. O.D. H		28	,	\$141	\$101	\$242
below adjunct cooker	00-356495	30%	pipe covering	OMA	25 ft. 10 in. O.D H		28		\$472	\$349	\$821
below convertor tank	00-356495		pipe covering	OMA	30 ft. 6 in. 0.D. H		28		\$389	\$243	\$632
just northeast of caustic tank	00-356495	30%	pipe covering	OMA	15 ft. 4 in. O.D. H		28	1	\$134	\$84	\$218
just northeast of caustic tank	00-356495		pipe covering	OMA	5 ft. 6 in. O.D. H		28		\$65	\$41	\$106
below convertor tank	00-356495		pipe covering	OMA	60 ft. 4 in. O.D. HF		28		\$535	\$335	\$870
below adjunct cooker	00-356495		pipe covering	OMA	55 ft. 6 in. O.D. H		28		\$714	\$446	\$1,160
below adjunct cooker	00-356495		pipe covering	OMA	60 ft. 4 in. O.D. H		28		\$535	\$335	\$870
behind caustic tank-against south wall	00-356495		pipe covering	OMA	16 ft. 8 in. O.D. HF		28		\$226	\$162	\$388
behind caustic tank-against south wall	00-356499		wrapped cardboard/paper pipe	AMO	8 ft. 8 in. O.D. HF		28		\$113	\$81	\$194
center E to W-along beam-near ceiling	00-356603		pipe covering	OMA	90 ft. 6 in. O.D. Pl	L	28		\$1,168	\$730	\$1,898
east side-mash filter-near floor	00-356603		pipe covering	OMA	6 ft. 6 in. O.D. Pl		28	1111	\$78	\$49	\$127
east side-mash filter-near floor	00-356603		pipe covering	OMA	6 ft. 4 in. O.D. Pl		28		\$54	\$33	\$87
east wall-near adjunct cooker-at floor	00-356603	30%	pipe covering	OMA	4 ft. 10 in. O.D Pl	L	28	111	\$75	\$56	\$131
below adjunct, convertor & mash tub tanks	00-356603	30%	pipe covering	OMA	60 ft. 10 in. 0.D Pl	L	28	111	\$1,132	\$838	\$1,970
east wall-near adjunct cooker-at floor	00-356603	30%	pipe covering	AMO	22 ft. 6 in. O.D. Pl	L	28	111	\$286	\$178	\$464
convertor tank	07-356483	35%	boiler/tank insulation	OMB	600 sq.ft.		28	111	\$16,950	\$13,578	\$30,528
	07-356484	40%			•		28	111	•	·	,
	07-356485	40%					28				1
adjunct cooker	08-356486	40%	boiler/tank insulation	OMB	600 sq.ft.		28		\$16,950	\$13,578	\$30,528
• • • • • • • • • • • • • • • • • • • •	08-356487	40%	•				28		7 ,	•	•
	08-356488	40%					28				
mash tub	09-356489		boiler/tank insulation	OMB	600 sq.ft.		28		\$16,950	\$13,578	\$30,528
muon tub	09-356490	50%	morror, carre rilactorion	Ų.,. U	000 041161		28		0.57750	2.27510	,

HALL-KIMBRELL ENVIRONMENTAL INC.

Page 47



ASBESTOS ASSE

H-K Building #: 21

Project Number: 0980193E

Project: G. HEILEMAN BREWERY "E"
Date Inspected: 03/21/89
Inspector: TIM SWARTZ

_

Building Number: 21/22

Building Name: BREWHOUSE/STOCK CELLARS

SEATTLE, WASHINGTON

Building Type: BREW/STOCK Year Constructed: 1948

	09-356491	0%	1				28 111			
caustic tank	10-356492	50%	boiler/tank insulation	OMB	500 sq.ft.		28 111	\$14,125	\$11,315	\$25,440
	10-356493	50%			•		28 111	•	•	•
	10-356494	50%]				28 111			
below adjunct cooker	11-356496	40%	mjp on pipe covering	OMA	25 6 in. O.D.	HPS/R	28 111	\$967	\$568	\$1,535
below convertor tank	11-356496		mip on pipe covering	OMA	35 4 in. O.D.	HPS/R	28 111	\$983	\$546	\$1,529
just northeast of caustic tank	11-356496	40%	mjp on pipe covering	OMA	2 6 in. O.D.	HPS/R	28 111	\$77	\$45	\$122
below mash tub	11-356496		mip on pipe covering	OMA	30 4 in. O.D.	HPS/R	28 111	\$843	\$468	\$1,311
below adjunct cooker	11-356496	40%	mip on pipe covering	OHA	6 10 in. O.D.	HPS/R	28 111	\$376	\$235	\$611
just northeast of caustic tank	11-356496	40%	mjp on pipe covering	OMA	8 4 in. O.D.	HPS/R	28 111	\$225	\$125	\$350
below adjunct cooker	11-356496	40%	mjp on pipe covering	OMA	27 4 in. O.D.	HPS/R	28 111	\$758	\$421	\$1,179
south of mash filter	11-356496	40%	mjp on pipe covering	OMA	2 8 in. O.D.	HPS/R	28 111	\$96	\$57	\$153
below convertor tank	11-356496	40%	mjp on pipe covering	OMA	5 6 in. O.D.	HPS/R	28 111	\$193	\$114	\$307
below mash tub	11-356496	40%	(mjp on pipe covering	OMA	14 6 in. O.D.	HPS/R	28 111	\$542	\$318	\$860
	11-356497	50%	1				28 111			
	11-356498	50%	1				28 111			
below adjunct, convertor & mash tub tanks	21-356604	60%	mjp on pipe covering	OMA	10 10 in. O.D.	PL	28 111	\$626	\$391	\$1,017
center E to W-along beam-near ceiling	21-356604	60%	mip on pipe covering	OHA	10 6 in. O.D.	PL	28 111	\$387	\$227	\$614
east wall-near adjunct cooker-at floor	21-356604	60%	mip on pipe covering	OMA	6 6 in. O.D.	PL	28 111	\$232	\$136	\$368
east wall-near adjunct cooker-at floor	21-356604		mip on pipe covering	OMA	2 10 in. 0.D.	PL	28 111	\$125	\$78	\$203
•	21-356605	60%	1				28 111			
	21-356606	60%					28 111			

AREA COMMENTS

AREA NUMBER: 05

AREA # 04 TOTAL \$78,521 \$60,463 \$138,984

AREA AVERAGE % ASBESTOS: 30%

The materials are in fair condition with localized contact and water damage. The materials are approximately 1' to 10' from the floor. At a minimum, it is recommended that the materials be repaired and monitored. If removal is planned, extensive gross removal procedures are recommended. This appears to be a high traffic area.

										·		
LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	QUANTITY	UNITS OF MEASURE	PIPE ID	EXP POT	PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
north wall-by adjunct cooker	00-356495	30%	pipe covering	OMA	15 f	t. 4 in. O.D	. HPS/R	27	111	\$134	\$84	\$2
north wall-by adjunct cooker	00-356495	30%	pipe covering	OMA	10 f	t. 8 in. O.D	. HPS/R	27	111	\$141	\$101	\$2
north wall-by adjunct cooker	00-356495	30%	pipe covering	OMA	10 f	t. 12 in. O.	D HPS/R	27	111	\$220	\$169	\$3
outh wall-behind caustic tank	00-356495	30%	pipe covering	OMA	30 f	t. 6 in. 0.D	. HPS/R	27	111	\$389	\$243	\$
outh wall-behind caustic tank	00-356495	30%	pipe covering	OMA	10 f	t. 4 in. O.D	. HPS/R	27	111	\$89	\$56	\$
outh wall-behind caustic tank	00-356495	30%	pipe covering	OMA	20 f	t. 10 in. O.	D HPS/R	27	111	\$377	\$279	\$
outh wall-behind caustic tank	00-356499	20%	wrapped cardboard/paper pipe	OMA	10 f	t. 10 in. O.	D HPS/R	27	111	\$189	\$140	\$
ext to mash tub	00-356603	30%	pipe covering	OMA	22 f	t. 6 in. O.D	. PL	27	111	\$286	\$178	\$
ext to adjunct cooker	00-356603	30%	pipe covering	OMA	27 f	t. 6 in. 0.D	. PL	27	111	\$350	\$219	:
ext to convertor tank	00-356603	30%	pipe covering	AMO	12 f	t. 6 in. O.D	. PL	27	111	\$156	\$97	\$
ext to adjunct cooker	00-356603	30%	pipe covering	OMA	25 f	t. 8 in. O.D	. PL	27	111	\$354	\$253	\$

AREA DESCRIPTION: 3rd Floor-Part #21-Yank Top Room

HALL-KIMBRELL ENVIRONMENTAL INC.

Page 48

06/09/89



ASBESTOS ASSES SURVEY

H-K Building #: 21

Project Number: 0980193E

Project: G. HEILEMAN BREWERY "E"

Date Inspected: 03/21/89 Inspector: TIM SWARTZ Building Number: 21/22

Building Name: BREWHOUSE/STOCK CELLARS

SEATTLE, WASHINGTON

Building Type: BREW/STOCK Year Constructed: 1948

next to adjunct cooker	00-356603	30%	pipe covering	OMA	12 ft. 4 in. O.D.	PL	27 111	\$107	\$67	\$174
next to mash tub	00-356603	30%	pipe covering	OMA	40 ft. 4 in. O.D.	PL	27 111	\$357	\$223	\$580
next to mash tub	00-356603	30%	pipe covering	OMA	7 ft. 8 in. 0.D.	PL	27 111	\$99	\$71	. \$170
next to convertor tank	00-356603	30%	pipe covering	OMA	12 ft. 8 in. O.D.	PL	27 111	\$170	\$121	\$291
next to convertor tank	00-356603	30%	pipe covering	OMA	12 ft. 4 in. O.D.	PL	27 111	\$107	\$67	\$174
north wall-by adjunct cooker	11-356496	40%	mjp on pipe covering	OMA	5 4 in. O.D.	HPS/R	27 111	\$140	\$78	\$218
south wall-behind caustic tank	11-356496	40%	mjp on pipe covering	OMA	2 4 in. O.D.	HPS/R	27 111	\$56	\$31	\$87
south wall-behind caustic tank	11-356496	40%	mjp on pipe covering	OMA	6 10 in. O.D.	HPS/R	27 111	\$376	\$235	\$611
north wall-by adjunct cooker	11-356496		mjp on pipe covering	OMA	1 8 in. O.D.	HPS/R	27 111	\$48	\$28	\$76
south wall-behind caustic tank	11-356496		mjp on pipe covering	OMA	2 6 in. O.D.	HPS/R	27 111	\$77	\$45	\$122
	11-356497	50%				•	27 111			
•	11-356498	50%					27 111			
south wall-behind caustic tank	20-356600	70%	mjp on wrapped cardboard/paper	OMA	6 10 in. O.D.	HPS/R	27 111	\$376	\$235	\$611
	20-356601	60%				•	27 111			
	20-356602	0%					27 111			
next to mash tub	21-356604	60%	mjp on pipe covering	OMA	6 8 in. O.D.	PL	27 111	\$289	\$170	\$459
next to convertor tank	21-356604		mjp on pipe covering	OMA	4 8 in. O.D.	PL	27 111	\$193	\$113	\$306
next to adjunct cooker	21-356604		mjp on pipe covering	OMA	6 4 in. O.D.	PL	27 111	\$169	\$94	\$263
next to adjunct cooker	21-356604		mjp on pipe covering	OMA	8 8 in. O.D.	PL	27 111	\$385	\$226	\$611
next to mash tub	21-356604		mip on pipe covering	OMA	8 6 in. O.D.	PL	27 111	\$309	\$182	\$491
next to convertor tank	21-356604		mjp on pipe covering	OMA		PL	27 111	\$56	\$31	\$87
next to adjunct cooker	21-356604		mip on pipe covering	OMA		PL	27 111	\$464	\$273	\$737
next to mash tub	21-356604		mjp on pipe covering	OMA		PL	27 111	\$337	\$187	\$524
next to convertor tank	21-356604		mjp on pipe covering	OMA		PL	27 111	\$155	\$91	\$246
	21-356605	60%					27 111			
	21-356606	60%					27 111			

AREA COMMENTS

AREA # 05 TOTAL \$6,955 \$4,387 \$11,342

The materials are in good condition with minor contact damage. The materials are approximately 1' to 12' from the floor. At a minimum, it is recommended that the materials be repaired and monitored. If removal is planned, extensive gross removal procedures are recommended. This appears to be a high traffic area.

******	AREA NUMBER: 06	AREA DESCRIPTION: 4th Floor-Part #21-Grain Hopper Room	AREA AVERAGE % ASBESTOS: 42%	******
			····	·

LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	QUANTITY	UNITS OF MEASURE	PIPE ID		PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL
along south & east walls	00-356608	50%	pipe covering	OMA	4 f	t. 4 in. O.D	. HPS/R	27	111	\$36	\$22	\$58
along south & east walls	00-356608	50%	pipe covering	OMA	22 f	t. 6 in. O.D	. HPS/R	27	111	\$286	\$178	\$464
along south & east walls	00-356608	50%	pipe covering	OMA	100 f	t. 12 in. O.I	HPS/R	27	111	\$2,202	\$1,693	\$3,89
closet next to south doorway-at ceiling	00-356608	50%	pipe covering	OMA	5 f	t. 6 in. O.D	. HPS/R	27	111	\$65	\$41	\$10
closet west of elevator	00-356608	50%	pipe covering	OMA	10 f	t. 6 in. O.D	. HPS/R	27	111	\$130	\$81	\$21
south wall-above exit & elevator	00-356608	50%	pipe covering	OMA	20 f	t. 6 in. O.D	. HPS/R	27	111	\$260	\$162	\$42
east center area-next to east wall	00-356612	0%	wrapped cardboard/paper pipe	OMA	24 f	t. 6 in. O.D	. DW		- 1			
along south & east walls	00-356730	40%	pipe covering	OMA	90 f	t. 12 in. O.I	D DW	27	111	\$1,982	\$1,524	\$3,50

HALL-KIMBRELL ENVIRONMENTAL INC.

Page 49



ASBESTOS ASSE

Building Number: 21/22

Building Name: BREWHOUSE/STOCK CELLARS

SEATTLE, WASHINGTON

Building Type: BREW/STOCK Year Constructed: 1948

Project: G. HEILEMAN BREWERY "E"
Date Inspected: 03/21/89
Inspector: TIM SWARTZ

along south & east walls	19-356732	50% mjp on pipe covering	OHA	4 12 in. 0.D.	DW 27 111 27 111	\$303	\$190	\$493
along south & east walls along south & east walls	22-356609 22-356609	0% mjp on pipe covering 0% mjp on pipe covering	OMA OMA	6 6 in. O.D. 4 12 in. O.D.	27 111 HPS/R 27 111 HPS/R 27 111	\$232 \$303	\$136 \$190	\$368 \$493
	1	10%			27 111 27 111			

AREA COMMENTS

AREA # 06 TOTAL \$5,799 \$4,217 \$10,016

The materials are in good condition with minor contact and water damage. The materials are approximately 1' to 16' from the floor. At a minimum, it is recommended that the materials be repaired and monitored. If removal is planned, extensive gross removal procedures are recommended. This appears to be a low traffic area

******	AREA NUMBER: 07	AREA DESCRIPTION: 5th Floor-Part #21	AREA AVERAGE % ASBESTOS: 43%	*****
L	·			

LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	UNITS OF QUANTITY MEASURE	PIPE ID	EXP POT		REMOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
southwest area-by scales southeast corner southwest area-by scales	00-356613 00-356617 23-356614 23-356615 23-356616	10%	pipe covering wrapped cardboard/paper pipe mjp on pipe covering	OMA OMA OMA	8 ft. 4 in. O.D. 12 ft. 6 in. O.D. 2 4 in. O.D.		27 27 27	111 111 111 111	\$71 \$156 \$56	\$45 \$97 \$31	\$116 \$253 \$87
southeast corner	24-356618 24-356619 24-356620	60% 60% 60%	mjp on wrapped cardboard/paper	OMA	2 6 in. 0.D.	DW	27 27	111 111 111	\$77	\$45	\$122

AREA COMMENTS

AREA # 07 TOTAL \$360 \$218 \$578

The materials are in good condition with minor contact and water damage. At a minimum, it is recommended that the materials be repaired and monitored. If removal is planned, glove bag removal procedures are recommended. This appears to be a low traffic area.

*****	AREA NUMBER: 08	AREA DESCRIPTION: Ground Floor	********

LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	QUANTITY	UNITS OF MEASURE	PIPE ID	EXP POT	PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
spent grain room-south wall south stairwell-at ceiling stock cellar H-against east wall	03-356469 03-356469 03-356469 03-356470	0%	pipe covering pipe covering pipe covering	OMA OMA OMA	6 f	t. 12 in. (t. 12 in. (t. 12 in. (D.D RS/R	12 12 12 12	IV IV	\$330 \$132 \$881	\$254 \$102 \$677	\$584 \$234 \$1,558

HALL-KIMBRELL ENVIRONMENTAL INC.

Page 50



ASBESTOS ASSE

H-K Building #: 21

Project Number: 0980193E

Date Inspected: 03/21/89 Inspector: TIM SWARTZ

AREA COMMENTS

Project: G. HEILEMAN BREWERY "E"

03-356471

Year Constructed: 1948 12 IV

Building Number: 21/22

Building Type: BREW/STOCK

AREA # 08 TOTAL \$1,343 \$1.033 \$2,376

Building Name: BREWHOUSE/STOCK CELLARS

SEATTLE, WASHINGTON

The material is in good condition. The material is approximately 9' from the floor. At a minimum, it is recommended that the material be maintained and monitored. If removal is planned, glove bag removal procedures are recommended. This appears to be a high traffic area.

****** ***** AREA NUMBER: 09 AREA DESCRIPTION: 2nd Floor AREA AVERAGE % ASBESTOS: %

LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	QUANTITY	UNITS OF MEASURE	PIPE ID	EXP POT	PL		REPLACEMENT COSTS	TOTAL COSTS
north brew kettle south brew kettle mezzanine level-whirlpool tank	00-999999 00-999999	x	boiler/tank insulation boiler/tank insulation boiler/tank insulation	OMB OMB	180 s 180 s 630 s	q.ft.				\$5,085 \$5,085 \$17,798		\$9,158 \$9,158 \$32,055

AREA COMMENTS

AREA # 09 TOTAL \$27,968 \$22,403 \$50.371

The material has a metal covering, making sample collection impossible. At a minimum, it is recommended that the material be maintained and monitored. If removal is planned, extensive gross removal procedures are recommended. This appears to be a high traffic area. This material has a stainless steel covering.

****** AREA NUMBER: 10 ******* AREA DESCRIPTION: 3rd Floor-Tank Top Room AREA AVERAGE % ASBESTOS: %

LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	QUANTITY	UNITS OF MEASURE	PIPE ID	EXP POT	PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
mash tub adjunct cooker convertor tank caustic tank	00-99999 00-999999 00-999999	X X	boiler/tank insulation boiler/tank insulation boiler/tank insulation boiler/tank insulation	OMB OMB OMB OMB	152 sc 152 sc 152 sc 152 sc	q.ft. q.ft.		•		\$4,294 \$4,294 \$4,294 \$4,294	\$3,440 \$3,440	\$7,734 \$7,734 \$7,734 \$7,734

AREA COMMENTS

\$30,936 AREA # 10 TOTAL \$17,176 \$13,760

The material has a metal covering, making sample collection impossible. At a minimum, it is recommended that the material be maintained and monitored. If removal is planned, extensive gross removal procedures are recommended. This appears to be a high traffic area.

> BUILDING # 21 TOTAL \$231,255 \$176,138 \$407,393

HALL-KIMBRELL ENVIRONMENTAL INC.

Page 51